UNCLASSIFIED

AD NUMBER

AD367498

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED



SECKET

GUNS AND MOUNTS PHOTOGRAPHIC INDEX

	TEST "A" & "B"	DACE	b
	U.S.S. ARKANSAS (EB-33)	PAGE	71.Y \$8000
	12"/50 Cal. Trunnion Block 12"/50 Cal. Trunnion Block	7	REPORT DIRECTLY THROUGH omic Support Agency D. C. 20301
AA-CR 234-1991-4		8	Ω ₇ α α
AA-CR 93-1987-10		9	7. Join 1.
	20mm Mount No. 8	10	REPORT THROUGH
AA-CR 93-1987-12 AA-CR 93-1996-1		11	취문 집다
AA-CR 93-1996-2	20mm Nount No. 8	12	4 F 5 7
AA CD OS 1004 3	20mm Mount No. 7	13	OF THIS EQUEST rector fense At
AA CD 02 1004 /	20mm Mount No. 7 20mm Mount No. 5 Periscope Turret No. 5	14	S C C C C C C C C C C C C C C C C C C C
AA-CR 93-1990-4	20mm Moulit No. 5	15	T OS at
WW-CH 37-1730-2	Periscope Turret No. 5	16	ES OF THIS REPOR L REQUEST THROU Director Defense Atomic S Washington, D. C
	U.S.S. NEW YORK (BB-24)		COPIES SHALL R Di De
AB-CR 234-2207-8	Holding Down Clip Turret No. 5	17	S H
AB-CR 68-2981-1	Llevating Screw Turret No. 3	18	OBTAIN USERS
AB-CR 68-2981-2	Elevating Screw Turret No. 3	19	ER TA
AB-CR 82-4222-6	Elevating Screw Turret No. 2		BC US
	Elevating Screw Turret No. 2		\ O
	Elevating Screw Turret No. 2		MAY
	Elevating Screw Turret No. 2		∑ ⊔
	Llevating Screw Turret No. 2	24	ES IED
	U.S.S. NEVADA (BB-36)		AGENCIES
BA-CR 68-36-9	5"/38 Twin Mount No. 7	25	₹ 8
BA-CR 68-44-4	20mm Twin Mount Port Side Aft	26	GOVERNMENT DDC. OTHER
BA-CR 148-277-7	40mm Mount No. 3	27	AF TH
BA-CR 148-277-9	5"/38 Mount No. 2	28	ξo
BA_CR 03_318_/	511/38 Mount No. 8	29	ر <u>س</u>
BA-CB 03-318-11	5"/38 Mount No. 8 20mm Mount Starboard Side Aft	30	50
AA-CR 60-150-/	5"/38 Mount No. 7	31	ថ្មីជី
	20mm Mount No. 17	32	භ් <mark>♥</mark>
AA-CR 97-1535-2	20mm Kount No. 7		FRO
AA-CR 97-1535-3	20mm Mount No. 7	33 34	Market Control
		34 35	
AA-CR 97-1535-4	20mm Mount No. 18 20mm Mount No. 18	35 36	
AA-CR 97-1535-5		36 27	
AA-CR 97-1535-8	20mm Mount No. 20	37 38	
AA-CR 93-1996-6	5"/38 Mount No. 7	38 30	
AA-CR 93-1996-7	5"/38 Mount No. 1	39 +	JAN 1965
SECRET		Downgraded at 12	3 I IAN die
	- Italy	Not automatically	declassified

Enclosure (D) to Director Ship Material Serial 001500.

Page 1 of 219 pegatic Value IV.

This document contains information affecting the Satisfaction of the United States with page 1 of 219 pegatic Value IV.

Defence of the United States with page 1 of the page 1 of 1 of the IV.

Pegationage Laws, Title 18, U. S. California in and Its transmission or the revelation of its transmission or

GUNS AND MOUNTS PHOTOGRAPHIC INDEX (Cont'd)

	TEST HAN & HBH	PAGE
	U.S.S. NEVADA (BB-36) (Cont'd)	PAGE
AA-CR 93-1996-8	5"/38 Mount No. 1	40
AA-CR 93-1996-9	5"/38 Mount No. 1	41
	5"/38 Mount No. 2	42
AA-CR 93-1996-11	40mm Mount No. 3	43
AA-CR 93-1996-12	40mm Mount No. 3	44
AA-CR 93-1998-1	5#/38 Mount No. 8	45
AA-CR 93-1999-2	5"/38 Mount No. 1	46
AA- CR 9 3-1 999-3	5"/38 Mount No. 2	47
AA-CR 93-1999-4	40mm Mount No. 3 5"/38 Mount No. 8 5"/38 Mount No. 1 5"/38 Mount No. 2 5"/38 Mount No. 8	48
	U.S.S. INDEPENDENCE (CVI-22)	
BA-CR 97-313-1	40mm Mount No. 5	49
BA-CR 97-313-3	40mm Mount No. 4	50
BA-CR 97-313-6	40mm Mount No. 8	51
BA-CR 97-313-8	40mm Mount No. 9	52
BA-CR 97-313-9	20mm Mount No. 6	53
BA-CR 97-313-11	20mm Mount No. 2 and No. 4	54
BA-CR 97-414-2	20mm Mount No. 1	55
	40mm Mount No. 2	56
AA-CR 81-1669-10	40mm Mount No. 2	57
AA-CR 81-1669-11	40mm Mount No. 2	58
AA-CR 81-1669-12 AA-CR 81-1670-1	40mm Mount No. 2	59
AA-CR 81-1670-1	20mm Mount No. 6	60
AA-CR 81-1670-2	40mm Mount No. 4	61
AA-CR 81-1670-3	40mm Mount No. 4	62
AA-CR 81-1670-4	40mm Mount No. 4	63
AA-CR 81-1670-5		64
	40mm Mount No. 8	65
	40mm Mount No. 9	66
	40mm Mount No. 9	67
AA-CR 81-1670-9	40mm Mount No. 9	68 60
AA-CR 81-1670-10	40mm Mount No. 1	69 70
AA-CR 81-1670-11	40mm Mount No. 1	7 0
AA-CR 81-1670-12	20mm Mount No. 1	71 72
AA-CR 92-1779-6	40mm Mount No. 9	72 73
AA-CR 92-1779-7	40mm Mount No. 9	73
AA-CR 92-1779-9	40mm Mount No. 9	74

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 2 of 219 pages. Volume IV.

GUNS AND MOUNTS PHOTOGRAPHIC INDEX (Cont'd)

	TEST "A" & "B" (Cont'd)	
		PACE
	U.S.S. INDEPENDENCE (CVL-22) (Cont'd)	
0. 00 300- 30		
AA-Ch 92-1779-10	40mm Mount No. 9	75
AA-CR 92-1779-11	40mm Mourit No. 9	76
AA-CR 92-1779-12	40mm Mount No. 9	77
AA-CR 92-1780-1	40mm Mount No. 9	78
AA-CR 92-1780-3	40mm Mount No. 9	79
AA-CR 92-1780-4	40mm Mount No. 9	80
AA-CR 92-1780-5	40mm Mount No. 9	81
AA-CR 92-1780-6	40mm Mount No. 9	82
AA-CR 92-1780-7	40mm Mount No. 9	83
	40mm Mount No. 9	84
	40mm Mount No. 9	85
	40mm Mount No. 9	86
AA-CR 92-1781-8		87
	40mm Mount No. 9	88
AA-CR 92-1781-10	40mm Mount No. 9	89
	U.S.S. PLNSACOLA (CA-24)	
AD_CD 07 160/ 1	ON /EE Manual No. O	
AD_CD 07-160/ 3	8#/55 Mount No. 2	90
AD .CD .CO 140/	8"/55 Mount No. 2 8"/55 Mount No. 2	91
AD-CR 07 146/ E	8"/)) Mount No. 2	92
AD-CE 07 1664 6	Weather Seal Mount No. 2	93
TB-ON OG 1404 G	8"/55 Mount No. 2	94
AB=UR 97-1084-7	8"/55 Mount No. 2	95
AB-CH 9/-158/-8	8"/55 Mount No. 2	96
AB-CH 97-1084-9	8"/55 Mount No. 2	97
AB-CR 97-1684-10	8"/55 Mount No. 2	98
AB-CR 97-1684-11	8"/55 Mount No. 2	99
AB-CR 97-1085-1	8"/55 Mount No. 2	100
AB-CR 97-1685-2	8"/55 Mount No. 2	101
AB-CR 97-1685-4		102
AB-CR 97-1685-5	8"/55 Mount No. 2	103
AB-CR 9/-1685-6	8"/55 Mount No. 2	104
AB-CR 97-1685-7	8"/55 Mount No. 2	105
AB-CR 97-1685-8	8"/55 Mount No. 2	106
AB-CR 97-1685-9	8"/55 Mount No. 2	107
AB-CR 97-1685-10	8"/55 Mount No. 2	108
AB-CR 97-1685-11	8"/55 Mount No. 1	109

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 3 of 219 pages. Volume IV.

GUNS AND MOUNTS PHOTOGRAPHIC INDEX (Cont'd)

	TEST "A" & "B"	
	U.S.S. PENSACOLA (CA-24) (Cont'd)	PAGE
AB-CR 97-1685-12	8"/55 Mount No. 1	110
AB-CR 97-1686-1	8"/55 Mount No. 1	111
AB-CR 97-1686-2	$8^{\eta}/55$ Mount No. 1	112
AB-CR 97-1686-3	8"/55 Mount No. 1	113
AR-CR 97-1686-5	911 /55 Marint No. 3	114
AB-CR 97-1686-6	8 ⁿ /55 Mount No. 1 8 ⁿ /55 Mount No. 1	115
AB-CR 97-1686-7	8"/55 Mount No. 1	116
AB-CR 97-1686-8	8"/55 Mount No. 1 8"/55 Mount No. 1 8"/55 Mount No. 1	117
AB-CR 97-1686-9	8"/55 Mount No. 1	118
AB-CR 97-1686-11	8"/55 Mount No. 1	119
AB-UK 97-1080-12	8"/55 Mount No. 1	120
AB-CR 97-1687-1		121
AB-CR 97-1687-2	8"/55 Mount No. 3	122
AB-CR 97-1687-3	8"/55 Mount No. 3	123
AB-CR 97-1687-4	8"/55 Mount No. 3	124
AB-CR 97-1687-5	8"/55 Mount No. 3	125
AB-CR 97-1687-6	8"/55 Mount No. 3	126
AB-CR 97-1687-7	8"/55 Mount No. 3	127
AB-CR 97-1687-8	8"/55 Mount No. 4	128
AB-CR 97-1687-9	8 ⁿ /55 Mount No. 4	129
	U.S.S. SALT LAKE CITY (CA-25)	
AA-CR 76-1926-10	8"/55 Mount No. 1	130
44 00 0/ 300/ 33	AH / F F 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	131
AA-CR 76-1926-12	8"/55 Mount No. 1	132
AA-CR 76-1927-1	8"/55 Mount No. 1	133
AA-CR 76-1927-2	8"/55 Mount No. 1	134
AA-CR 76-1927-3	8"/55 Mount No. 1	135
AA-CR 76-1927-4	8"/55 Mount No. 1 8"/55 Mount No. 2	136
AA-CR 76-1927-5	8"/55 Mount No. 1	137
AA-CR 76-1927-6	8"/55 Mount No. 2	138
ANTOR (DELYCIE)	O"/DD MOUNT NO. 2	139
	8"/55 Mount No. 2	140
AA- CR 76-1927-9	8 ^H /55 Mount No. 2	141
	U.S.S. STACK (DD-406)	
AA-CR 93-1998-11	5"/38 Mount No. 1	142
AA-CR 93-1998-12	5"/38 Mount No. 1	143
	e per minimum energy on	ربند

SECHET

Enclosure (D) to Director Ship Material Serial 001500.

Page 4 of 219 pages. Volume IV.

GUNS AND MOUNTS PHOTOGRAPHIC INDEX (Cont. d)

	TEST "A" & "B"	PACE
	U.S.S. HUGHES (DD-410)	
AB-CR 76-1931-8 AB-CR 76-1931-9	5"/38 Mount No. 2 5"/38 Mount No. 2	144 145
	U.S.S. WAINWRIGHT (DD-419)	
AA-CR 93-1998-7 AA-CR 93-1998-8 AA-CR 93-1998-9 AA-CR 93-1998-10	5"/38 Mount No. 1 5"/38 Mount No. 2 5"/38 Mount No. 3 5"/38 Mount No. 4	146 147 148 149
	U.S.S. WILSON (DD-408)	
AA-CR 93-2070-1 AA-CR 93-2070-4	5#/38 Mount No. 2 5#/38 Mount No. 3	150 151
	U.S.S. RHIND (DD-404)	
AA-CR 93-2070-5 AA-CR 93-2070-6 AA-CR 93-2070-7 AA-CR 93-2070-8 AA-CR 93-2070-9 AA-CR 93-2070-11 AA-CR 93-2070-12	5"/38 Mount No. 1 5"/38 Mount No. 1 5"/38 Mount No. 2 5"/38 Mount No. 2 5"/38 Mount No. 2 5"/38 Mount No. 2 5"/38 Mount No. 2	152 153 154 155 156 157 158
	U.S.S. RALPH TALBOT (DD-390)	
AA-CR 93-1998-2 AA-CR 93-1998-3 AA-CR 93-1998-4	5"/38 Mount No. 3 5"/38 Mount No. 2 5"/38 Mount No. 2	159 160 161
AA-CR 76-1927-10 AA-CR 76-1927-12	U.S.S. SKATE (SS-305) 40mm Single Mount 40mm Single Paunt	162 163

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 5 of 219 pages. Volume IV.

GUNS AND MOUNTS PHOTOGRAPHIC INDEX (Cont'd)

	TEST "A" & "B"	to 2. M
	U.S.S. CRITTLINDEN (APA-77)	PA IL
AA-CR 93-1998-5 AA-CR 93-1998-6	20mm Mount No. 8 20mm Mount No. 8	164. 165
	U.S.S. CASCONADE (APA-85)	
AB-CR 100-4210-4 AB-CR 100-4210-5 AB-CR 100-4210-7 AB-CR 100-4210-8 AB-CR 100-4210-9	40mm Mount No. 4 20mm Mount No. 8 5"/38 Mount 5"/38 Mount 20mm Mount No. 1	166 167 168 169 170

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 6 of 219 pages. Volume IV.



b.b.6. Altahend (ch-33) - After able those up view of h. 1/50 Gel., trumben thock right you torward end of the right you of Turnet Ro. A showing the broken section. Photo. No. An-th-234-1-91-1.

医异丙亚甲基

Enclosure (b) to birector ship Maderial Lacrie 1 # 2000.

... Page 7 of 219 pages. Volum IV.

4.13

The second secon



U.S.S. ARKANSAS (BB-33) - After Able Close up view of 12"/50 Cal. Trunnion Block Right Gun Turret No. 4, showing the cracked trunnion block afterside and clearance between cap square and trunnion. Photo. c. AA-CR-234-1991-2.

Enclosure (D) to Director Ship Material Serial 001500.

Page 8 of 219 pages. Volume IV.



Table . Addition (sh-23) - Aft - Allo Close up view of 15%/50 Onla trummion . Llock right One Turnet No. 4 specing the distortion of the knite edge. 16 to. to. to. Ametically 1914.

11411


Includes (1) to Director off Material Serial October

lege 9 of 119 pages. Volume, W.

The Secretary of the second

h :

4.5 9



U.b.C. Abraham (140-35) - After allo General view of 10 M2 Atto be. Cond No. 8 showing how Mt., the 9 had harred and Mechanian man beat by Thing design from Turnet Re. 5. Photo. No. Am-Ch-59-1907-10.

出表处在技术

. selection of a tendirector Ship Material serial . 2000.


Page 10 of \$19 pages. Volume IV.



U.D.C. ADDANCE (20-33) - After After After Close up of 20 Marks, how 8 showing tent burnel and mus necessions. Thoso, No. AA-Ch-53-1987-12.

Enclosure (D) to Director Ship Material Serial 001500.

Page 11 of 219 pages. Volume IV.




U.L.D. ARKANDAG (FE-33) - After Alle Close up of 20 Md Mt. No. 8, snewing distorted megazine that was struck by flying debris and scorching of paint. Photo. No. An-Ch-95-1990-1.

22555

Enclosure (1) to Director Dhip Material Derivat Old; Old.


Page 37 of 710 pages. Volum 4...



U.S.S. ARTAROAD (N-33) - After Able General view of 20 km Mt. No. 7, showing distorted megazine and burned empty case bag. Photo. No. AA-Ch-93-1996-2.

Enclosure (D) to Linector (Ai) Material Serial 201500.

There 1 of 219 pages. Volume IV.




U. ... Abrahlan a desire and property of Close of of act and are are represented to the Photos to a desired and the Photos to a desired party of the Photos to a desired party and the photos to a desired party a

BECHEZ

Inchorage (I) to Director thip Natural Serial 2015 e.

Page 14 of 219 pagers. Volume W.



Clove up view of 20 MM Mt. No. 5, showing distorted magazine and empty case bag burned off.

Photo. No. AA-CR-93-1996-4.


LECELI

Company of the second of the s

は、日本のでは、日

Enclosure (L) to Director Ship Katerial Serial Octions.

Page 15 of 219 pager. Volume IV.



U.S.S. ARKANSAS (EB-33) - After Able Close up view of the periscope on top of Turret No. 5, 12"/50 cal. showing how it was bent by flying debris.
Photo. No. AA-Ck-93-1996-5.

Enclosure (D) to Director Ship Material Serial 001500.

Page 16 of 219 pages. Volume IV.




U.S.S. NEW YORK (FB-34) - After Baker Close up view of No. 2 holding down clip in Turret, No. 5. Showing increased clearance. Photo. No. Ab-CR-234-2207-8.

<u>21655</u>T

Enclosure (L) to Director Ship Material Scriel School.

Page 17 of .10 paper. Vehine W.

421)




U.J.S. NEW YURK (En. 3%) - After Baker Close up view of left elevating screw in 14"/45 Cal., Turret No. 3. Showing Housing Cover Securing Screws sheared off and exposed Finion Gear. Photo. No. AB-CR 68-2981-1.

4 4 9 4 **4 1**

speciation (i) to birector Ship Material Serial 001500.


Page 18 of 219 pages. Volume IV.

. 4213



U.O.S. NEW YORK (BB-34) - After Baker Close up view of left elevating screw in 1/27/A) Cal., Turnet No. 3. Showing Housing Cover because Screws showed off and exposed Finner Gers Thoso, how the 68-2981-20

The second of th




U.C.: Reh YORK (Bb-3.) - After Baker Close up view of left elevating screw in 1A"/A5 Cal., Turret No. 2. Showing housing Cover Lecuring Screws sheared off and exposed Pinion Gear.
Photo. No. Ab-Gh-82-4222-6.

21111

Inclosure (b) to birecar whip kateris? herid colpec.

Page 20 of 219 pages. Volume IV.




U.S.S. NEW YORK (Bb-34) - After Leker Close up view of left eleveting screw in 14"/45 Cel., Turret Fo. 2. Showing Lleveting Screw Housing with upper half kace in tact.
Photo. No. Ab-CR-82-4222-7.

PFCB17

Enclosure (1) to Director Ship Material Serial Coltoc.

Fage 21 of 219 pager. V dume IV.

4.17




U.S.S. NEW YORK (BB-34) - After Baker Close up view of left elevating screw in 14"/45 Cal., Turret No. 2. Showing Elevating Screw Housing with upper Ball Race in tact.

Photo No. AB-CR-82-4222-8

SECRAT

Enclosure (D) to Director Ship Material Serial 001500.

Page 22 of 219 pages. Volume IV.



U.S.S. NIM YORK (18-34) - After liker View of the left Heveting Seven In 14"/45 Cal., Turnet No. 2. Showing the broken oscillating nut and the displaced lover hall-Race with the lover hegating nut. Photo. No. 65-Ch-85-42:1-9.

SEVELI

bucknown (b) to Lirector this material heries " 1000.

Page 23 of 219 pages. Volume IV.




U.S.S. NEW YORK (BE-34) - After Baker View of the Left Elevating Screw in 14"/45 Cal., Turret No. 2. Showing the broken oscillating mut. Photo. No. AE-CR-82-4222-10.

SECHLI

Enclosure (D) to Director Ship Material Serial 001500.

Page 24 of 219 pages. Volume IV.

. 1213



U.S.S. NAVALA (Bh-36) - Before Atle View of 5"/38 Cal. twin mount No. 7 trainer's station showing condition before Test "A". Fhoto. No. BA-Ch-68-36-9.

SECKET

Enclosure (L) to Director thip Material Serial Oction.

Page 25 of 219 pages. Volume IV.




Value NIVALA (11-30) - , expressible View of 20 kM twin mount located at frame 1.5, port side, showing condition of the mount lefere rest "A". Froto, No. 82-63-68-25-7.

アファファフ

buclosure de to licector Dal, Escardal perial Octyon.

Page 26 of 219 pager. Volume IV.



U.S.S. NEVALA (BE-36) - before Able Condition of right side of No. 3 40 MM Mount before Test "A". Photo. No. BA-CR-148-277-7.

Enclosure (L) to Director Ship Material Serial 1500.


Page 27 of 219 pages. Volume IV.



U.S.S. NFVAIA (bh-36) - before able Condition of No. 2 5"/38 Cal. twin mount before Test "A".
Photo. No. BA-CR-148-277-9.

Enclosure (L) to Lirector Ship Material Serial 001500.

luge 28 of 219 peges. Volume IV.




U.D.b. MIVALA (11-36) - before Able View of 5"/38 (al. twin mount No. 8 mointer's station showing condition lefore Test "A". Photo. No. nk-Ch-0 - 218-11.

斯里萨尼亚里

enclosure (a) to birector Ship Material Serial 001500.

Page 29 of 219 pager. Volume IV.




U.S.S. NEVADA (BE-36) - Before Able View of 20 MM twin mount located at frame 125, starboard side, showing condition of the mount before Test "A". Photo. No. BA-CE-93-318-11.

SECHET

Enclosure (D) to Director Ship Material Serial 001500.

Page 30 of 219 pages. Volume IV.



U.S.S. NEVADA (BB-36) - After Able General view of 5"/38 Mt. No. 7 showing the damage to the Gun Port Bucklers. Photo. No. AA-CR-60-150-4.

BECRET

Enclosure (D) to Director Ship Material Serial 001500.


Page 31 of 219 pages. Volume IV.



6.5.5. NEWDOK (Fn-36) - After Atle General view of 20 MM Twin Mt. No. 17 showing the demolished spanks. Photo. No. AA-CR-97-1535-1.

obbbbb

Enclosure (b) to Director Ship Material Serial Oction. Page 32 of 219 pages. Volume IV.



U.S.S. NEVADA (Bb-36) - After Able General view of 20 MM Twin Mt. No. 7 showing the camplished stand. Photo. No. Aa-Ch-97-15/1-2.


http://docume to the Director Stip Contental Cortal Oction.
Page 33 of 219 pages. Volume IV.



U. J.S. NeVADA (.h-36) - After Able General view of 20 MM Twin Mt. No. 7 showing the demolished stand. Thoto. No. 4A-GR-97-1539-3.

Enclosure (L) to Director Ship Material Serial (001500.

Page 34 of 219 pages. Volume IV.



U.S.S. MAVADA (ED-36) - After Able General view of 20 MM Twin Mt. No. 18 showing the cent aplinter shield and the distorted bicycle hand pripe. Photo. No. AA-On-97-1535-4.

SECEET

Enclosure (b) to Director Chip Material Dering of 1990.

Tage 25 of 219 pages. Volume IV.

4,72




U.C.S. NEVADA (ED-36) - After Able Front view of 20 am Twin Mt. Co. 16 showing the bent splinter visible. Photo. No. AA-CR-27-1936-5.

includes (a) to three or bhip interful sert

Tuge 36 of 719 peres. Volume 1.

4




U.S.S. NEVADA (BB-36) - After Able General view of 20 MM Twin Mt. No. 20 showing the bent splinter shield. Photo. No. AA-CR-97-1535-8.

· No. in the Control of the Control

Enclosure (D) to Director Ship Material Serial 001500.

Page 37 of 219 pages. Volume IV.




U.S.S. NEVALA (bb-36) - After Able General view of 5"/28 Mt. No. 7, showing the damage to the our Fort Bucklers. Photo. No. AA-CR-C3-1006-6.

SECHET

Enclosure (D) to Director Ship Material Derial 001500.

Page 38 of 219 pages. Volume IV.



U.S.S. NEVADA (Bb-36) - After Able Close up of damage to the Right Gun Port Buckler of 5"/38 Mt. No. 1.
Photo. No. AA-CR-93-1996-7.

Enclosure (D) to Director Ship Material Serial 001500.

Page 39 of 219 pages. Volume IV.

Control of the Contro



U.S.D. REVADA (BI-56) - After Able Close up of damage to the Left Gun Fort buckler of 5"/38 lit. No. 1. Thoto. No. AA-Ch-55-166-2.

SELRET

Enclosure (L) to Director Ship Material Serial 001500.

Page 40 of 219 pages. Volume IV.




U.S.S. NEVALA (Bb-36) - After Able Close up showing the torn Gun Port Bucklers of 5"/38 Mt. No. 1. Notice the paint scorching priterns on the roof plate and the un barrels. Photo. No. AA-CH-93-1996-9.

SECEET

Enclosure (b) to Director Chip Material Serial 001500.

Page 41 of 119 pages. Volume IV.



U.C.S. NHVADA (bloom) - Attemplas 5"/38 Mt. No. 2 slowing specific of the Roof Plate in int. Photo. No. AA-Ch-10; -1..

SECEET

Enclosure (L) to Director Ship Material or 1 1 1 1 0.

Page 42 of 219 pager. W share JV.

4713



U.S.S. NEVADA (EB-36) - After Able General view of 40 MM Twin Mt. No. 3 showing the broken glass of the train lag meter and the distorted open sight. Photo. No. AA-CK-93-1996-11.

SECRET

Enclosure (D) to Director Ship Material Serial 001300 Page 43 of 219 pages. Volume IV.




U.S.S. NEVADA (BB-36) - After Able Close up view of the Right Gun Barrel of 40 MM Twin No. 3. This design on the barrel was caused by whipping action of wire rope.

Photo. No. AA-CR-93-1996-12.

Enclosure (b) to Director Ship Material Serial 001500.

Fage 44 of 219 pages. Volume IV.




A CR 9 3- 1998+1

U.S.S. NEVADA (BB-36) - After Able General view of 5"/38 Mt. No. 8 showing the damage to the Gun Port Bucklers. Photo. No. AA-CR-93-1998-1.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 45 of 219 pages. Volume IV.




U.S.S. NEVADA (BE-36) - After Able Interior view of 5"/38 Mt. No. 1 showing the pinched oil lines at the trainer's station. Photo. No. AA-CR-93-1999-2.

BELLET

Enclosure (U) to Director Ship Material Serial 001500.

Page 46 of 219 pages. Volume IV.




U.S.S. NEVADA (BB-36) - After Able Interior view of 5%/38 at. No. 2 showing the ruptured cover of the Fower Failure Solenetd.

Photo. ho. Ak-Ck-93-1966-3.

1 2 C E & 12

Parchamas e 1869, the borne of the care of the combination of the Care

Same Profix S pones. Toltar W.



U.D.S. NEVALA (bb-36) - After Able Interior view of 5"/38 Mt. Po. 8, showing the pinched oil lines at the trainer's station. Photo. No. AA-CR-93-1999-4.

<u>SEGLIT</u>

Enclosure (L) to Director Ship Material Perial (201500.

Page 48 of 219 pages. Volume IV.



U.S.B. THEREBRACK (CVI-No) - Length with Condition of No. 5 AS NV Lount before Test "A". Photo. No. Executive7-313-1.


SECHLI

Company of the second of the s

Enclosure (1) to Director ohip Enterial Serial Colo C.

Page 49 of 719 pager. Volume IV.


a c 13



U.S.S. INDEPENDENCE (CVL-22) - Before Able Condition of No. 4 40 MM Mount before Test "A". Photo. No. BA-CR 97-313-3.

Enclosure (D) to Director Ship Material Serial OC1500.

Page 50 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - refore Able Condition of No. 8 40 MM Bount before Test "A". Photo. No. BA-CR-97-313-6.

Enclosure (D) to Director Ship Material Serial 001500.

Fage 51 of 219 pages. Volume IV.



U.S.S. INTEPENDENCE (CVL-22) - seriore atte Condition of No. 9 40 Ms Mount before Test "A". Photo. No. BA-CR-97-313-8.

PFCRFI

Enclosure (L) to Director Ship Material Serial (6016)00.


Page 52 of 219 pages. Volume JV.



U.S.S. INDEPENDENCE (CVL-22) - Before Able Condition of No. 6 20 MM Mount before Test "A". Photo. No. BA-CR-97-313-9.

Enclosure (D) to Director Ship Material Serial 601500.


Page 53 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - Pefore Able Condition of 20 MM Mounts, No. 2 and 4 before Test "A".
Photo. No. bA-CP-97-313-11.

<u>ShualT</u>

Enclosure (D) to Director Ship Material Serial OC1500.




W.S.S. INDEPENDANCE (CVL-22) - Lefore Atle Condition of No. 1 20 MM Nount before Test "A". Photo. No. bA-C: 17-401-...

SECKLT

Enclosure (L) to Director Ship Material Serial 3 1930.

Page 55 of 219 pages. Volume IV.



U.O.O. INDEPENDENCE (CVL-22) - After Able View of the Gun Mechanism of 40 BM Twin Mt. No. 2 Showing the forward armunition suide missing. Photo. No. 34-01-81-160-9.

アモアなです

inclosure (L) to Director Oldy Material Serial 001500.


Page 16 of Ply under Volume TV.



U.S.S. THOLPENDENCE (CVI-22) - After Able View of the sheared off elevating locking pin of AC VM twin Mt. No. 2. This view was taken from the left rear. Photo. No. AA-th-21-1669-10.

Enclosure (D) to Director Shire a collaborated 001:00.

From 17 of the pears. Volume IV.




U.D.D. INDEPENDENCE (CVI-22) - After Able General view of 40 MM Twin Mt. No. 2 Showing the forward right ammunition guide missing. The bent case deflector of the right gun can be clearly seen. The shattered glass of the train lag meter can also be seen in this view.

Photo. No. AA-CK-SI-1669-11.

2 b a b b T

Enclosure (D) to Director Ship Material Serial S01500.


Page 58 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVI-22) - After Able General view of 40 MM Twin Mt. No. 2 Showing the damaged pointers upon sight and the distorted Guard Rail Trainer's Side. Photo. No. AA-CR-81-1669-12.


Enclosure (D) to Director Ship Material Serial 001500.

Page 59 of 219 pages. Volume IV.



U.C.D. INDEPENDENCE (CVL-22) - After Able General view of 20 MM Mt. No. 6 showing the missing Mk. 14 Sight and Shoulder Rest. Photo. No. 14-CR-SI-1670-1.

block 1 T had birector Ship Not relat Serial 001500.



U.S.C. INDEPENDENCE (CVI-22) - After Able Close up of 7,0 MM Twin Mt. No. 4 showing the bent automatic loads. S. Photo. No. AA-CL-81-1670-2.

Enclosure (D) to Director , hip keterini , erial $C(\mathbb{R}^{n_0})$.

Page 61 of 219 payer. Volume IV.




U.C.C. THATCHIEGO (CVI.C.) - 140 m.l. Clone up 40 MB ht. No. 4 showing the cent conserving lossers and ready service make 1100co her Fredress-key.

2 1 H . . . 1

Implopture (1) to librorto: Chip Material Series objects.

Pege 62 of 219 pages. Volume IV.

6.24




U.S.S. INDEPENDENCE (CVI-22) - After Able Front view of AO MM Twin Mt. No. & showing the tent open sight guard. The sheared off elevation securing pin can be seen to the right of the elevating arc. Fhoto. No. AA-CR-81-1670-4.

SICRET

Enclosure (b) to birector this material Serial CO1500.

Page 63 of 219 pages. Volume IV.

4713




U.S.S. INDEPENDENCE (CVI-FR) - Arter Alle General view of ZG MA Twin At. No. A showing the bent sutometic loaders and the distorted sponson shield. Photo. No. AA-Ch-81-1670-5.

SECRET

Enclosure (D) to Director Ship Material Marial Colbut.


Page 64 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - After Able General view of 40 MM Twin Mt. No. 8 showing the bent autometic loaders, the damaged open sights and the distorted sponson shield. Photo. No. AA-CR-81-1670-6.

Enclosure (D) to Director Ship Material Serial CO1500.

Page 65 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVI-22) - After Atle General view of 40 M/ Twin Mt. No. 9 showing the left truncion out of its housing. An aircraft fuel tank and a white pipe can be seen in the foreground. Photo. No. AA-CR-81-1570-7.

Enclosure (L) to Director Ship Baterial Serial Ocal Co.

Page 66 of 219 pages. Volume IV.




U.L.S. INDEFINITION (CH-22) - After Ale General view of 40 MM lwh Mt. Fo. 9 showing the cented Cun Flice. An aircreft fuel tank can be seen in the forground. The white pipe across the Cun Mechanism is a piece of debris. Fhoto. Fo. FA-Ch-21-1170-8.

EECELT

Enclosure (D) to Director Sldp Meterial Paris 1 Colf 60.

Page 67 of 219 pages. Volume 1v.




U.S.S. INDEPENDENCE (CVL-22) - After Able Front view of 40 M% Twin Mt. No. 9 showing the distorted carriage checks. Fhoto. No. AACR-81-1670-9.

SACREI

Anchosure (D) to Director Ship Material Serial 001500.

Page 68 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVI-22) - After After After General view of AO MM Twin Mt. No. 1 showing the distortion of the trainer's open right and the ready service rack. The trainer sent is missing.


Fhoto. No. AA-Ch-81-1670-10.

SECRET

Anchogure (D) to Lirector this Esterial Cerial COlfera

Page 69 of 219 pages. Volume IV.

42:



U.S.S. INDEPENDENCE (CVL-22) - After Able General view of 40 MM Twin Mt. No. 1 showing the distortion of the trainer's open sight and the ready service rack.

Photo. No. AA-CR-d1-1670-11.

Enclosure (D) to Director Ship Material Serial 001500.

Page 70 of 219 pages. Volume IV.



U.S.S. INDEFENDENCE (CVL-22) - After Alle General view of 20 MW Lt. No. 1 showing the damage to the right splinter shield, cartridge bag, Wk. 10 sight and missing shoulder rest. Photo. No. AA-CF-81-1670-12.

Enclosure (D) to Director Ship Material Serial 001500.

Page 71 of 219 pages. Volume IV.



b. ...S. INDEPENDENCE (CVI-22) - After Able Front view of AO MM Twin No. 9 showing the displacement of the slide and the cleveting arc. Theto. No. AA-CR-92-1779-5.

SECELI

Enclosure (D) to Director Ship Material Serial 001500.

Page 72 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVI-22) - After Able Front view of 40 kM Twin No. 9 showing the distortion of the left carriage check and the displacement of the trunnion from the trunnion housing.

Photo. No. AA-CR-92-1779-7.

SEVEET

Enclosure (D) to Director Ship Material Serial 001500.

Page 73 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - After Able Front view of 40 MM Twin No. 9 showing the displaced elevating are and the distortion of the adjusting stop.

Photo. No. AA-CR-92-1779-9.

LILLEET

andlosure (D) to Director Ship Material Serial 001500.

Page 74 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVI-22) - After Able Right rear view of 40 MM Twin Mt. No. 9 showing the displaced elevating arc. Photo. No. AA-CR-92-1779-10.

Enclosure (D) to Director Ship Material Serial 001500.

Page 75 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVI-22) - After Able kight rear view of 40 MM Twin Mt. No. 9 showing the displaced Gum Mechanism and the distorted right carriage check. The trummion can be sen in the upper center. Photo. No. AA-CR-92-1779-11.

SECHET

Enclosure (D) to Director Ship Material Serial 001500.

Page 76 of 219 pages. Volume IV



U.S.S. INDEPENDENCE (CVL-22) - After Able Showing the misalignment of the case deflectors and case sjecting chaites of 40 MM Twin Rt. No. 9
Photo. No. AA-CR-92-1779-12.

SECKET

Enclosure (0) to Director (nip Meterial Serial 001500.

Page 77 of 219 pages. Volume IV.




U.S.S. INDEPENDENCE (CVL-22) - After Able View of 40 MM Twin Mt. No. 9 - looking downward at the right trunnion and right cap square. The displaced elevating arc can be seen in the background. Photo. No. AA-CR-92-1780-1.

SECELI

Enclosure (D) to Director Ship Material Serial 001500.

Page 78 of 219 pages. Volume IV.




U.S.S. INDEPENDENCE (CVL-22) - After Able View of the left carriage check and trunnion of 40 MM Twin Mt. No. 9 Photo. No. AA-CK-92-1780-3.

SECEET

Charles and the


Enclosure (D) to Director Ship Material Serial 001500.

Page 79 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - After Able Showing the left carriage check and outer push rod of 40 MM Twin Mt. No. 9. Photo. No. AA-CR-92-1780-4.

Enclosure (D) to Director Ship Material Serial 001500.



U.S.S. INDEPENDENCE (CVL-22) - After Able View looking downward at the right trunnion. The stripped trunnion threads can also be seen. 40 MM Twin Mt. No. 9 Photo. No. AA- CR-92-1780-5.

A CONTRACTOR OF THE STATE OF TH

のでは、100mm

Enclosure (D) to Director Ship Material Serial 001500.


4213



U.S.S. INDEPENDENCE (CVL-22) - After Able Front view of 40 MM Twin Mt. No. 9 Showing the distorted right carriage check and the displaced elevating arc. The right push rod is also missing. Photo. No. AA-CR-92-1780-6.

Enclosure (D) to Director Ship Material Serial 001500.

Page 82 of 219 pages. Volume IV.




U.S.S. INDEPENDENCE (CVI-22) - After Able Front view of 40 MM Twin Mt. No. 9 Showing the distorted left carriage check and displaced trunnion. The bent elevating cam follower can be seen against the carriage check. Photo. No. AA-CR-92-1780-7.

SECHET

Enclosure (D) to Director Ship Material Serial 001500.

Page 83 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - After Able Front view of 40 MM Twin Mt. No. 9 Showing the distorted left carriage check and the bent cam follower. Photo. No. AA-CR-92-1780-9.

PFOFFI

Enclosure (L) to Director Ship Material Serial 001500.

Page 84 of 219 pages. Volume IV.




U.S.t. INDEPENDENCE (CVL-22) - After Able Rear left view showing bent core ejecting chute and the displaced case ejector. Photo. No. AA-CR-92-1780-1%. AOMM Twin Mount No. 9.

SECLLI

beclowere (b) to Linector oldp Material

Fede 85 of 21% paper. 1000 000

A Control of the Cont



U.S.S. INDEPENDENCE (CVL-22) - After Able General view of 40 MM Twin Mt. No. 9. The barrels have been removed in preparation for removing the gun and slide.

Photo. No. AA-CR-92-1781-7.

SECHET

Enclosure (L) to Director Ship Material Serial 001500.

Fage 86 of 219 pages. Volume IV.




U.S.S. INDEPENDENCE (CVI-22) - After Able
General view taken from the rear of 40 MM Mt.
No. 9 showing the distorted carriage checks.
Note the scars to the right of the adjustable
stop. These scars were made by the elevating arc.
The slide has been removed in preparation the mount
for shipment to the Naval Cun Factory.
Photo. No. AA-CR-92-1781-8.

SECKET

Enclosure (D) to Director Ship Material Serial 001500.

Page 87 of 219 pages. Volume IV.

4213




U.S.S. INDEPENDENCE (CVL-22) - After Able General view taken from the rear of 40MM Twin Mt. No. 9
Showing the distorted carriage checks. Photo. No. AA-CR-92-1781-9.

FFGFFI

Enclosure (b) to Director Ship Material Serial 001500.


Page 88 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVI-22) - Aft r Able General view taken from the rear of 40 kM Twin Mt. No. 9 Showing the distorted carriage checks. Photo. No. AA-CR-92-1761-10.

Enclosure (D) to Director Ship Material Meson.

Page 59 of 219 pages. Jakuse IV.



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of Mt. No. 2. Showing after mection of Horizontal Thrust Rollers and Race exposed.

Photo. No. AB-CR-97-1684-2.

SECHET

Enclosure (D) to Lirector Ship Material Serial 001500.

Page 90 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of the Stbd. after section of weather seal on Mt. No. 2. Showing exposed Horisontal Thrust Roller Race. Photo. No. AB-CR-97-1684-3.

Enclosure (D) to Director Ship Material Serial 001500.

Page 91 of 219 pages. Volume IV.



B.C.D. Parks ACOIA (desc.) - And a labor Clare of view of the interpretation of the weather read at the last of a charactery expense of propher read at the last read read many time of the last read of the last

 $a \in \mathbb{R}^{n}$

Lett LT

Inclosure (L) to blession only discuss of the papers of the




U.S.S. PENSACOLA (CA-24) - After Baker Close up view of the Fwd. center line section of the weather seal on Mt. No. 2. Showing torn and crushed weather seal housing.

Photo. No. AB-CR-97-1684-5.

Enclosure (D) to Director Ship Material Serial 001500.


Page 93 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of the after centerline section of Mt. No. 2. Showing exposed inner (smoot Roller Path, and exposed section of the Horizontal Thrust Roller Roller, Photo. No. A = (2-97-158)(25)

SECALL

Enclosure (i) is the end of H_{ij} and H_{ij} and H_{ij}



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of after centerline section of Mt. No. 2. Showing exposed Horizontal Thrust Bearings. Photo. No. AB-CR-97-1684-7.

SECRET

Enclosure (D) to Director Ship Material Serial 0 7500.

Page 95 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-2A) - After Haker Close up of the after port section of No. 2 Mt. Showing exposed Horizontal Thrust hearings. Photo. No. AB-CR-97-1684-8.

PFCFFI

Enclosure (b) to Director Ship Material Serial OC1500.

Page 96 of 219 pages. Voltage IV.

4713



U.S.S. PENSACOLA (CA-24) - After Able Close up of the after port section of No. 2 Mt. Showing the exposed Horisontal Thrust Bearing and distorted Weather Seal Housing. Photo. No. AB-CR-97-1684-9.

SECHET

Enclosure (L) to Director Ship Material Serial 001500.

Page 97 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker General view of Port side of Mt. No. 2. Showing torn weather seal housing and exposed Forizontal Thrust Bearings. Photo. No. AB-CE-27-1684-10.

PFFFFT


and course (D) to Director this to tested Seriel Solider.

Page 98 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of port Fwd, section of the Foundation and Weather Seal of Mt. No. 2 Showing Weather Seal crushed by the downward thrust of the mount. Fhoto, No. AB-CR-97-1684-11.

Enclosure (D) to Director Ship Material Serie' 001500.



U.S.S. PENSACOLA (CA-24) - After Baker Close up - looking up at training pinion and training rack of Mt. No. 2. Showing sheared bolts on train pinion Housing Cover Plate and clearance between pinion teeth and training rack.
Photo. No. AB-CR-97-1685-1.

SECRLI

Enclosure (D) to Director Ship Material Serial 001500.

Page 100 of 219 pages. Volume IV.



U..... FINEACLE (CA-22) - After raker close up of the Fwd. end of the pewcer transfer room Mt. No. 2. Shewir the amount the ceck was displaced and tall hearing that fall from the train tearing noscolly.

Photo. No. Ab-(R-97-1885-2.

SEGALL

Enclosure (E) to Darwer or Ship Material Derivation (Clark).

Page 1:2 of 219 pages. Volume IV.

. . .



U.S.S. PHISACOLA (CA-24) - After Baker Close up view of the Mechanical Train Indicator Gear, Mt. No. 2. Showing how much it was disengaged from the rack and the exposed balls and race. Photo. No. Ab-Ck-97-1689-4.

PFFFF

Enclosure (D) to Director Ship Material Serial 001500.

Page 102 of 219 pages. Volume IV.



U.S.S. PENSACCIA (CA-24) - After baker Close up of the balls, ball race and rack of Mt. No. 2. Showing displaced balls and ball race. Photo. No. Ab-CR-97-1689-5.

Enclosure (D) to Director Ship Material Serial 001500.

Page 103 of 219 pages. Volume IV.




U.S.S. PENSACOLA (CA-24) - After Baker Close up looking up at the training rack stbd. fwd. in Mt. No. 2. Showing the torn flange under the training rack. Photo. No. AB-CR-97-1685-6.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 104 of 219 pages. Volume IV.




U.S.S. PENSACOLA (CA-24) - After Baker Close up of training rack and support flange in 8"/55 Mt. No. 2. Showing how the flange was torn by the downward force of the training rack. Photo. No. AB-CR-97-1685-7.

SECAET

Exclosure (D) to Director Ship Material Serial 001500.

Page 105 of 200 pages. Volume IV.

#214



U.S.S. PENSACOLA (CA-2A) - ACTOR STOP General view of upper powder transfer room 8"/55 Mt. No. 2. Showing backled deck on after side of the powder transfer room. Photo. No. AB-CR-97-1685-8.

SECEET

Enclosure (D) to Director Ship Material Serial 001500. Page 106 of 219 pages. Volume IV.

4213



U.S.S. PLNSACOIA (CA-24) - After Baker Close up of training rack and balls and ball race on after center line side of 8"/55 Cal. Mt. No. 2. Showing exposed ball race and displaced balls and how much the sections overlapped. Photo. No. AB-CR-97-1685-9.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 107 of 219 pages. Volume IV.



U.S.S. PHNSACOLA (CA-24) - After Baker Close up view of left side of powder transfer room 8"/55 Mt. No. 2. Showing dent in powder trunk and bent rransfer tray. Photo. No. AB-CR-97-1685-10.

Enclosure (D) to Director Ship Material Serial 001500.

Page 108 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of the after section under the overhang of 8m/55 Cal. Mt. No. 1 showing the torn weather seal housing. Photo. No. AB-CR-97-1685-11.

RECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 109 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker General view of Port Fwd. Section of the weather seal on 8"/55 Cal. Mt. No. 1 showing torn weather seal housing and exposed packing. Photo. No. APCR-97-1685-12.

Enclosure (D) to Director Ship Material Serial 001500.

Page 110 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of port side weather seal of 84/55 Cal. Mt. No. 1 showing displaced weather seal packing. Photo. No. AB-CR-97-1686-1.

Enclosure (D) to Director Ship Material Serial 001500.

Page 111 of 219 pages. Volume IV.




U.S.S. PENSACOLA (CA-2A) - After Baker Close up view of elevating nut housing in 8"/55 Cal. Mt. No. 1 showing displaced trunn on cap squares and sheared cap square bolt.
Photo. No. AB-CR-97-1386-2.

PFCFFI

Enclosure (D) to Director Ship Material Serial 001500.

Page 112 of 219 pages. Volume IV.



U.S.S. PINSACOLA (CA-2A) - After Baker Close up view of elevating gear 8"/55 Cal. Mt. No. 1 showing disensaged Oldham Coupling between the "B" End Hydraulic Unit and the illevating Nut. Photo. No. AB-CR-97-1686-3.

SECELT

inclosure (a) to Director Ship Material Serial 001500.

Page 113 of 219 pages. Volume IV.

4713




U.S.S. PENSACOLA (CA-24) - After Baker General view of the left upper Ponder Transfer Trunk 8"/55 Cal. Mt. No. 1 showing ruptured bulkhes: and sheared bulkhead bolts. Photo. No. AB-CK-97-1686-5.

FFFFF

Enclosure (D) to Director Ship Material Serial 001500.

Page 114 of 219 pages. Volume IV.



U.S.S. PENSAUOLA (CA-24) - After Baker Close up view of lift breech plug of 8"/55 Cal. Mt. No. 1 showing bent carrier hinge pin. Photo. No. AB-CR-97-1686-6.

SRCRET

Enclosure (D) to Director Disp Material Derival 001500.

Page 115 of 219 pages. Volume IV.

4213



U.D.D. Prindera (Ch-12) - After laker Close up view of training rack in 8"/ 5 (al. Mt. No. 1 showing displaced and over lapping of the Ball Ruces. Photo. No. Ab-CR-97-1686-7.

SECALT

Encionare (D) to the country being accepted contain containing the first of the parent Volume TV.



U.5.S. PENSACOIA (CA-24) - After Baker Close up view of training pinion housing in 87/55 Cal. Mt. No. 1 showing bolt sheared off lower housing cover plate. Fhoto. No. AB-CR-97-1686-8.

LECKLI

Enclosure (D) to Director Ship Meterial contel College.

Page 117 of 219 pages. Volume IV.




U.S.S. PENSACOLA (CA-24) - After Toper Close up view of training race in 80/ 5 Cal. Mt. No. 1 showing exposed balls and ball race. Photo. No. AB-CR-97-1686-9.

SLUBIT

Enclosure (L) to Director Ship Material Berial 0.100.


Page 118 of 219 pages. Volume IV.



1.5.5. PriDACOLA (CA-24) - After Able Close up view of training rack in 8"/55 Cal. Et. No. 1. Showing exposed ba s and ball race.
Those, No. AB-CR-97-1686-11.

<u>SECheT</u>

rnclosure (L) to Director . has taterial Serial 001500.



U.S.S. PENSACOLA (CA-24) - After Able Close up of training rack in 8"/55 Cal. Mt. No. 1. Showing exposed balls and ball races.

Photo. No. AB-CR-97-1686-12.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 120 of 219 pages. Volume IV.





U.S.S. PENCACOIX (CA-22) - After teker General view of weather seed of Mt. No. 3. Showing the shifting of the Dt., and chared bolts. (Sthd. side). Photo. No. AB-CR-97-1687-1.

E E C E I T

Anclosure (b) to Director Olip Anterial Lerich with 7. Page 171 of v19 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker General view of Fwd. section of weather seal, Mt. No. 3. Showing sheared bolt and shifting of the mt. Photo. No. AB-CR-97-1687-2.

SECLET

Enclosure (II) to Director Ship Material Serial 001500.

Page 122 of 219 pages. Volume IV.



J.S.S. PENSACOLA (CA-24) - After Baker General view of the port Fwd. section of weather scal Mt. No. 3. Showing exposed weather scal packing and crushed weather seal housing. Photo. No. AB-CR-97-1687-3.

Enclosure (D) to Director Ship Meterial Serial 001500.

Page 12 of 219 pages. Volume IV.

\$213



U.S.S. PhNSACOLA (CA-24) - After Paker Close up view of the training rack, lit. No. 3. Showing where the trainin rack shifted upward. Photo. No. Ab-Cr-97-1687-4.

SECHLI

Enclosure (L) to Linector Ship Material Serial 001500

Page 124 of 219 pages. Volume IV.




U.S.S. PHEACOLA (CA-.4) - after dater Close up view of the training rack of Mt. No. 3. Showing the amount the Fwd. center line section of the training rack shifted upward.

Photo. No. Ab-CR-97-1687-5.

Enclosure (D) to Director Ship Material Derial O(1900.

Page 125 of 219 pages. Volume IV.



U.S.S. PENSACOLA (CA-24) - After Baker Close up view of the train pinion housing, Mt. No. 3. Showing bottom of train pinion housing looking up. Photo. No. AB-CR-97-1687-6.

Enclosure (D) to Director Ship Material Serial 001500.

Page 126 of 219 pages. Volume IV.



U.S.S. PiNSACOLA (CA-24) - After Baker Close up view looking down on the safty link on .1 ht and center guns of Mt. No. 3. Showing type of breaks. Photo. No. AB-CR-97-1687-7.

Enclosure (D) to Director Ship Material Serial 001500.

Page 127 of 219 pages. Volume IV.



U.S.D. FERRACULA (Ch-M) - After softer close up view of the lower testing into housing plate of Mt. No. 4. Dhowing the missing bolt.
Photo. No. AB-CR-97-1687-8.

breichure (1), to Director Ship Material Serial 001500.

lare 128 of Mr peres. Volume IV.



U.S.S. PENNACOLA (CA-24) - After Baker Close up view of after atbd. section of No. 4 Mt. Showing exposed balls and ball race.
Photo. No. AB-CR-97-1687-9.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 129 of 219 pages. Volume IV.

4 13



U.S.S. SALT LAKE CITY (CA-25) - After Able View of 8"/55 Mt. No. 1 showing the blown out weather seal, right side.
Photo. No. AA-CR 76-1926-10.

SLOKET

Enclosure (D) to Director Ship Material Serial (001608)

Page 130 of 219 peges. Volume ${\rm NV}_{\star}$

4713



U.S.S. SALT IAKE CITY (CA-25) - After Able View of 8"/55 Mt. No. 1 showing the blown out weather seal, left side. Photo. No. AA-CR-76-1926-11.

SECLET

Enclosure (D) to Director Ship Material Serial 001500.

Page 131 of 219 pages. Volume IV.



U.S.S. SALT LAKE CITY (CA-25) - After Able Interior view of 8"/55 Mt. No. 1 showing the cracked and chipped paint on the lower end of the adjustable turnbuckle, pointer's side. Photo. No. AA-CR-76-1926-12.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.


Page 132 of 219 pages. Volume IV.



U.S.S. SAIT LAKE CITY (CA=25) - After Able Interior view of 8"/55 Mt. No. 1 showing the cracked paint on the upper end of the adjustable turnbuckle, pointer's side. Photo. No. AA-CK-76-1927-1.

Enclosure (D) to Director Ship Material Serial 001500.

Page 133 of 219 pages. Volume IV.



U.S.S. SALT LAKE CITY (CA-25) - After Able Interior view of 8"/55 Mt. No. 1 showing the excessive clearance between the cap square and the deck lug, pointer's side. Photo. No. AA-CR-76-1927-2.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 134 of 219 pages. Volume IV.



U.S.S. SALT LAKE CITY (CA-25) - After Able Interior view of 8"/55 Mt. No. 1 showing the cracked paint on the deak lug support, pointer's side. Photo. No. AA-CR-76-1927-3.

Enclosure (D) to Director Ship Material Serial 001500.

Page 135 of 219 pages. Volume IV.

4213



U.S.S. SALT LAKE CITY (CA-25) - After Able Interior view of 8"/55 Mt. No. 1 showing the excessive clearance between the slide and the deck lug, pointer's side.

Photo. No. AA-CR-76-1927-4.

Enclosure (D) to Director Ship Material Serial 001500.

Page 136 of 219 pages. Volume IV.



U.S.S. SALT LAKE CITY (CA-25) - After Able Interior view of 8"/55 Mt. No. 1 showing the excessive clearance between the cap square and deck lug, pointer's side.
Photo. No. AA-CR-76-1927-5.

SECHET

Enclosure (D) to Lineator Ship Material Serval (CD) C.



U.S.S. SAIT LAKE CITY (CA-25) - After Able Exterior view of the left gun of 8"/55 Mt. No. 2 showing the blown out weather seal and the chipped paint on the face plate, showing that the slide shifted to the left. Photo. No. AA-CR-76-1927-6.

SECHET

Enclosure (D) to Director Ship Material Serial 001500.

Page 138 of 219 pages. Volume IV.



U.S.S. SALT LAKE CITY (CA-25) - After Able Exterior view of right run of 8"/55 Mt. No. 2 showing the blown out weather seal. Photo. No. AA-CR-76-1927-7.

Enclosure (D) to Director Ship Material Serial 001500.

Page 139 of 219 pages. Volume IV.



U.S.S. SALT LAKE CTY (CA-25) - After Able Interior view of 8"/55 Mt. No. 2 showing the blown out weather seel, trainer's side. Photo. No. AA-CR-76-1927-8.

SECELI

Enclosure (D) to Director Ship Laterial Serial 001500.

Page 140 of 219 pages. Volume IV.




U.S.S. SALT LAKE CITY (CA-25) - After Able Interior view of 8"/55 Mt. No. 2 showing the blown out weather seal pointer's side. Photo. No. AA-CR-76-1927-9.

SECRET

Enclosure (b) to Director Ship Material Serial 001500.

Page 141 of 219 pages. Volume IV.



U.S.S. STACK (ID-406) - After Able General view of 5"/38 Cal. Mt. No. 1 showing torn Gun Port Bloomer and scorched exterior paint Photo. No. AA-CR-93-1998-11.

SECLET

Enclosure (D) to Director Ship Material Serial 001500.

Page 142 of 219 pages. Volume IV.




U.S.S. STACK (DD-406) - After Abla Close up of 5"/38 Cal. Nt. No. 1. Showing tora Gun Port Bloomer and scorched exterior paint. Photo. No. AA-CR-93-1998-12.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 143 of 219 pages. Volume IV.




U.S.S. HUGHES (DD-410) - After Baker Close up view of left cap square and bolt in Mt. No. 2., 5"/38 Cal. showing clearance between cap square and deck lug. Photo No. AB-CR-76-1931-8.

ELCLET

Enclosure (E) to Director Ship Material Serial 00:1500.

Page 144 of 219 pages. Volume IV.




U.S.S. HUCHES (DD-410) - After Baker Close up view of the left cap square bolt in Mt. No. 2., 5"/38 Cal. Showing the clearance where the bolt strecked to loosen the cap square. Photo. No. AL-Ch-76-1931-9.

SECHET

Enclosure (D) to Director Ship Material Serial 001400.

Page 145 of 219 pages. Volume IV.




U.S.S. WAINWRIGHT (LD-419) - After Able General view of 5"/38 Mt. No. 1, Showing burned gun port gas seal and scorched exterior paint caused by burning Gun Port Eleomer. Photo. No. AA-CR-93-1998-7.

SECRLT

Enclosure (D) to Director Ship Material Serial 001500.

Page 146 of 219 pages. Volume IV.




U.S.S. WAINMAIGHT (DD-419) - After Able Close up of 5"/38 Cal. Mt. No. 2. Showing scorched Gun Port and Gun Port Cas Seal. Photo. No. AA-UR-93-1998-8.

SECHET

Enclosure (D) to Director Ship Naterial Social 001500.


Page 147 of 219 pages. Volume IV.



U.S.S. WAINWRIGHT (DD-419) - After Able Close up of 5"/38 Cal. Mt. No. 3. Showing torn canvas top. Photo. No. AA-CR-93-1998-9.

Enclosure (D) to Director Ship Material Serial 001500.

Page 148 of 219 pages. Volume IV.



U.S.S. WAINERIGHT (DD-419) - After Alle #4 5"/38 Lount showing gun buckler turned away. Weather seal in gun port burned. Paint in vicinity of buckler turned by buckler. Exterior paint scorched by blast. Photo. No. AA-Ch-93-19/8-10.

SECRET

Enclosure (D) to Director Ship Material Serial OC15 44.

Page 149 of 119 pages. Volume IV.



U.S.C. WILLON (LD-408) - After Alle Close up of 5"/38 Cal. Mt. No. 2. Showing Gum Port Bloomer torm away and scorched exterior paint. Photo. No. AA-CR-93-2070-1.

SECHET

Enclosure (D) to Director Ship Material Serial (C1400).

Page 150 of 219 pages. Volume IV.

4213




U.S.S. WILSON (DD-408) - After Able Close up of 5"/38 Cal. Mt. No. 3. Showing exterior paint on projectile hoist, rammer and pointer's station scorched. Pheto. No. AA-CR-93-2070-4.

SECHET

Enclosure (D) to Director Ship Material Serial 001500.


Page 151 of 219 pages. Volume IV.



U.S.S. RHIND (DD-404) - After Able General view of 5"/38 Mt. No. 1 Showing remants of the Gum Port Bloomers and Sight Port Bloomers. Photo. No. AA-CR-93-2070-5.

Enclosure (D) to Director Ship Material Serial 001500.

Page 152 of 219 pages. Volume IV.



AACRJ - 2070 -


U.S.S. RHIND (DD-404) - After Able General view of 5"/38 Mount No. 1. Showing the remnants of the Gun Port Bloomers and the Sight Port Bloomers. Photo. No. AA-CR-93-2070-6.

SECRET

• :

Enclosure (D) to Director Ship Material Serial 001500.

Page 153 of 219 rages. Volume IV.




U.S.S. RHIND (DD-404) - After Able General view of the underside of 5"/38 Mt. No. 2. Showing the scorched paint and the ruptured hydraulic sump tank. The "dishing in" of the shield can be seen. Fhoto. No. AA-CR-93-2070-7.

PFFFT

Enclosure (1) to Director Ship Material Serial 0015.00.

Page 154 of 219 pages. Volume IV.


4213



U.D.S. RHIND (UD-404) - After Able View of the starboard side of 5"/38 Mt. No. 2. Showing the "dishing in" of the shield, access door and sump tank cover. Photo. No. AA-CK-93-2070-8.

Linchpanne (b) to Director Ship Material Serial 001500.


Here 105 of 219 pages. Volume IV.



U.S.S. RHIND (DD-404) - After Able
Interior view of 5"/38 Mt. No. 2
Showing the "dishing in" of the starboard shield. Photo. No. AA-CR-93-2070-9.

Enclosure (D) to Pirector Ship Material Serial 001500. SECRET

Page 156 of 219 pages. Volume IV.



U.D.... hHIND (LD-404) - After Able Interior view of 5"/38 Mt. No. 2 Showing the "dishing in" of the access door and after shield. Photo. No. AA-CR-93-2070-11.

<u>5 1 C E E T</u>

Enclosure (i) to Director Ship Material Serial Oc1500.

Page 157 of 219 pares. Volume IV.

4213




U.S.S. hHHMD (DD-AGA) - After Able Exterior view of 5"/38 Mt. No. 2 Showing the "dishing in" of the necess door and after sideld. Photo. No. 4A-CR-93-2070-12.

SECKET

Enclosure (D) to Director Ship Material Jerish Octpor.


Page 158 of 219 pages. Volume IV.



U.S.S. RALPH TALBOT (DD-390) - After Able 5"/38 Single Mt. No. 3 Showing the distorted Guard Rail on the Mount Platform, trainer's side. Photo. No. AA-CR-93-1998-2.

Enclosure (D) to Director Ship Material Serial 001500.


Page 159 of 219 pages. Volume IV.



U.S.S. RALPH TALBOT (DD-390) - After Able Exterior view of 5"/38 Mt. No. 2 Showing the "dishing in" of the after shield. Photos No. AA-CR-93-1998-3.

Enclosure (D) to Director Ship Material Serial 001500.

Page 160 of 219 pages. Volume IV.



U.S.S. RALPH TAIROT (DD-390) - After Able Exterior view of 5"/38 Mt. No. 2 Showing the "dishing in" of the after shield. Photo. No. AA-CR-93-1998-4.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 161 of 219 pages. Volume IV.



U. .S. SKA(E (SS-305) - After Able General view of the AD EM Single Mt. The gun mechanism, basell and slight bar can be seen.


Photo. No. 4A-Sk-7(-19/7-10.

2 1 <u>6 2 5 1</u>

Enclosure (b) to Director (hip Material Lerial 001500.

Page 162 of 219 pages. Volume IV.

4213



U.S.S. SKATE (SS-305) - After Able View of 40 MM Single Mt., showing the foundation intact.
Photo. No. AA-CR-76-1927-12.


SECRET

•:

Enclosure (D) to Director Ship Material Serial 201500.

Page 163 of 219 pages. Volume IV.

4. : 1



View showing a fill the too 8. This mount was former jamed in this position. Photos too marchettel 2-6.

PRUBLI

Enclosure (1) to Linector Ship Material werise $\gamma \sim 1^{n_0} + \epsilon$

Page 164 of 219 pages. Volume IV.



U.S.S. CRITTENDEN (APA-77) - After Able View showing 20 MM Mt. No. 2. The right splinter shield was jammed against the pedestal preventing training of the unit. Photo. No. AA-CR-93-1998-6.

SECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 165 of 219 pages. Volume IV.



U.S.S. CALCONALA (APA-85) - After baker General view of 40 kM, Mt., No. 4. Showing distorted Gun Platform and bent Sight and Sight Bar. Photo. No. 46-CK-100-4210-4.

Enclosure (D) to Director Ship Material Serial 001000 Page 166 of 219 pages. Volume IV.



U.S.S. GASCONADE (APA-85) - After Baker Close up view of 20 MM, Mt., No. 8 at Frame No. 135. Showing bent gun shield, broken linkage on firing cut out and outboard side of gun tub torn away. Photo. No. AB-Ch-100-4210-5.

•:

Enclosure (b) to Director Ship Material Serial 001500.

Page 167 of 219 pages. Volume IV.



U.S.S. MASCONADA (ALA-25) - After baker Close up view of 5"/23 Mt., rain Hardwheel Bracket. Showing broken securing bolts. Photo. No. AB-CH-100-4210-7.

5 k C k k T

Enclosure (D) to Director Ship Material Derial 001500.

Page 168 of 219 pages. Volume IV.



U.S.S. GASCONADE (APA-85) - After Baker Close up view of 5"/38 Cal. Mt. front shield. Showing left side dished in. Photo. No. AB-CR-100-4210-8.

SECKET

Enclosure (D) to Director Ship Material Serial 001500.

Page 169 of 219 pages. Volume IV.



U.S.S. GASCONADE (APA-85) - After Baker Close up view of 20 MM, Mt., No. 1. Showing broken firing stop linkage. Photo. No. AB-CR-100-4210-9.

Enclosure (D) to Director Ship Material Serial 001500.

Page 170 of 219 pages. Volume IV.

<u>secre</u> <u>t</u>

UNDERWATER ORDNANCE PHOTOGRAPHIC INDEX

TESTS "A" AND "B"

			
	NAGATO (Ex-Jan BB)	Page	
BACR87-360-8	Mine Mark 6 displayed on deck.	173	
	U.S.S. SARATOGA (CV3)		
BACR76-295-6	Torpedo Mark 13 in TBM on flight deck.	174	
BACR76-295-5	Mine Mark 24 in TRM on flight deck.	175	
BACR76-295-4	Mine Mark 24 in Normal Stowage.	176	
BACR76-295-3	Torpedoes Mark 13 in Normal Stowage.	177	
BACR76-295-2	Torpedoes in Normal Stowage.	178	
BACR76-295-1	Mine Mark 24 in hangar deck.	179	
BACR76-294-12	Torpedo Mark 13 on hangar deck.	180	
	U.S.S. INDEPENDENCE (CVL22)		
BACR76-295-7	Mine Mark 24 in TBM on flight deck.	181	
BACR76-295-8	Torpedo in plane on flight deck.	182	
BACR76-296-9	Service Allowance torpedoes in normal stowage.	183	
BACR76-291-11	Torpedo Mark 13 and Mine Mark 24 in ready stowage.		
BACR76-291-12	Mine Merk 24 in normal stowage.	185	
BACR87-2541-2	Damage to torpedoes in normal stowage.	186	
BACR87-2541-3	Damage to torpedoes in normal stowage.	187	
BACR87-2541-5	Damage to torpedoes in normal stowage.	188	
BACR87-2541-4	Damage to Mine Mark 24 in normal stowage.	189	
BACR87-2541-6	Damage to torpedoes in normal stowage.	190	
BACR87-2541-7	Damage to torpedoes in normal stowage.	191	
BACR87-2541-8	Torpedo Mark 13 and Mine Mark 24 in ready stowage.		
BACR87-2541-9	Torpedo Mark 13 from TBM on flight deck.	193	
BACR87-2541-10	Mine Mark 24 from TEM on flight deck.	194	
	U.S.S. WILSON (DD-399)		
BACR63-497-3	Torpedo bridle rigged on test torpedoes.	195	
	U.S.S. LAMSON (DD-367)		
BACR56-29-2	Placement of special weapons on fantail.	196	
	U.S.S. MUGFORD (DD-389)		
BACR8794"9	Placement of special weapons on fantail.	197	
SECRE!			
Enclosure (D) to Director Ship Material Serial 001500.			

Page 171 of 219 pages. Volume IV.

UNDERWATER ORDNANCE PHOTOGRAPHIC INDEX (Continued)

TESTS HAH & MBH (Continued)

	U.S.S. MAYRANT (DD-402)	Page
ABCR82-4220-10	Depth Charge Mark 6 broken from arbor.	198
ABCR82-4220-9	Depth Charge Mark 6 broken from arbor.	199
ABCR82-4220-8	Depth Charge Mark 6 broken from arbor.	200
AACR-1704-3	Bridle rigged on torpedoes.	201
	U.S.S. RALPH TALBOT (DD-390)	
AACR63-1703-10	Damage to phone box on torpedo tube mount.	202
AACR63-1703-8	Trainers seat on torpedo tube mount.	203
	U.S.S. RHIND (DD-404)	
AACR87-2540-7	Showing effect of the heat on depth charges.	204
AACR63-1695-9	Showing effect of the heat on torpedo tubes.	205
AACR92-1772-2	Showing forware movement of torpedoes.	206
AACR63-1703-1	Effects of blast in vicinity of detonator stowage.	207
	U.S.S. HUGHES (DD-410)	
AACR87-2539-1	Showing effects of heet on depth charges.	208
ABCR30-2062-4	Showing torpedoes part way out of barrels.	209
ABCR76-1930-7	Showing torpedoes part way out of barrels.	S10
ABCR76-1930-6	Showing torpedoes tube after decontamination.	211
ABCR76-1930-5	Showing torpedo stop tension links.	213 213
ABCR76-1930-3	Showing torpedoes part way out of barrels.	213 214
ABCR59-2996-2	Torpedo after removal from tube. Removing torpedo from tube.	215
ABCR29-2996-1	nemoving torpedo from tube.	210
r.	U.S.S. BRACKEN (APA-64)	
RACR87-359-5	Typical display of Mine Mark 6 on APA's.	21 6
	U.S.S. ARDC-13	
AACR98-1963-4	Torpedo tube spoon extension.	217
AACR98-1963-3	Torpedo tube spoon extension.	218
AACR98-1963-2	Torpedo tube spoon extension.	S19

<u>secret</u>

Enclosure (D) to Director Ship Material Serial 001500.


Page 172 of 219 pages. Volume IV.



U.S.S. NACATO (Ex-Joy 10) - cater to Display of Mine, Th. on neck. Photo. No. BA-Ch-87-- - - Y.

Enclosure (D) to Director Ship Sakered a start

Page 178 of 219 pages. 10 have 10




U.S.L. SARATOCA (CV=3) - Before Able Special Test Torpedo, Mk. 13 losded in TEM on flight deck. Photo. No. EA-CR-76-295-6.

SECRLI

Enclosure (D) to Director Ship Material Serial 001500.

Page 174 of 219 pages. Votume IV.




U.S.S. SARATOGA (CV-3) - Before Able Mine, Mk. 24 loaded in TBM on flight deck. Photo. No. BA-CR-76-295-5.

SECKET

Enclosure (D) to Director Ship Material Serial 001500.

Page 175 of 219 pages. Volume IV.



U.S.S. SARATOGA (CV-3) - Before Able Mine, Mk. 24 in normal stowage. Photo. No. BA-CR-76-295-4.

BECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 176 of 219 pages. Volume IV.


U.S.S. SARATOGA (CV-3) - Before Able Mk. 13 Special Test Torpedoes in normal stowage.

Photo. No. Ba-CR-76-PON-3.

SECKET

Enclosure (L) to sixed a self-lite wind as the lite.

lage 127 of the pages. Toleran 1%,



U.S.S. SARATOGA (CV-3) - Before Able Service Load Torpedoes in normal stowage. Photo. No. BA-CR-76-295-2.

Enclosure (D) to Director Ship Material Serial 001500.

Page 178 of 219 pages. Volume IV.



U.S.S. SARATEGA ((V-3) - Defore Alls Mine, Mk. 24 in hengue deck. Photo. No. BA-OR 7(-199-1.

SECRLI

Enclosure (D) to Director Ship Material werith sedject.

Page 179 of 219 press. Volume 17.



U. .b. SARSTOGA (CV-3) - Pefore Able Special Test Torocco, Mr. 13 on Pontan Crok. Thoto. No. Da-Ch Ma-19.-1.

Applopure 4.7 to Timestor Dip Entertal Corporation

Page 180 of 210 water. You we IT.



U.D.S. INDEFENDENCE (CVL-22) - Before Ablemine, Mk. 24 loaded in TBM on flight deck. Photo. No. BA-CR-76-295-7.

 $\underline{S} \not\subseteq \underline{U} \subseteq \underline{U} \subseteq \underline{U} T$

Enclosure (1) to Director Chip Material Serial 001500.

Page 181 of 219 pages. Volume IV.




U.S.S. INDEPLIABBLE (CVL-22) - Before Able Aircraft Torpedo loaded in plane on flight deck.
Photo. No. PA-CR-76-295-8.

SECLET

Enclosure (b) to director Ship Material Serial 001500.

Fare 182 of 219 pages. Volume IV.

4213



U.c.S. INDEPENDENCE (CVL-22) - Effere Rele Service Load Torpedoes in normal stormer. Photo. No. FA-CK-76-295-9.

SECHET

Enclosure (D) to Director Shdr Material Serial Oolf 00.

Face 107 of 219 pages. Volume IV.


4013



U.S.S. INDEPENDENCE (CVL-22) - Before Able Showing Aircraft Torpedo and Mine, Mk. 24 in ready stowage on hanger deck. Photo. No. BA-CR-76-291-11.

Enclosure (D) to Director Ship Material Serial 001500.


Page 184 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - Before Able Showing Mine, Mk. 24 in normal stowage. Comp. C-101-H. Photo. No. BA-CR-76-291-12.

SECKET


Enclosure (D) to Director Ship Material Serial 001500.



U.C.S. INDEPENDENCE (CVL-22) - After Able Damage to torpedo stowage compertment C-101B. Note some of the airflasks are in tact. Photo. No. AA-CR-27-2541-2.

Enclosure (D) to Director Ship Material Serial 001500.

Page 186 of 219 pages. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - After Able Service Lend Torpedoes in normal stowage. Comp. C-1018.

Photo. Fc. AA-CR-87-25A1-3.

SECRET

Enclosure (L) to Director Shir Material Serial 001500.

Fare 187 of 219 prizes. Volume IV.



U.S.S. INDEPENDENCE (CVL-22) - After Able Service Load Tompedoes in normal stowage. Comp. C-101B.
Photo. No. AA-CR-87-2541-5.

Enclosure (D) to Director Ship Material Serial 001500.



U.S.S. INDEPENDENCE (CVI-22) - After Able Showing Mine, Mk. 24 in normal stowage. Comp. C-101-B.
Photo. No. AA-CR-87-2541-4.

Enclosure (D) to Director Ship Material Serial 001500.



U.S.S. INDEPENDENCE (CVL-22) - After Able Service Load Torpedocs in normal stowage. Comp. C-1018. Showing welded air flask segments.

Photo. No. AA-CR-87-2541-6.

Enclosure (D) to Director Ship Material Serial 001500.

Tage 190 of 219 pages Volume IV.

27.7



U.E.S. INDEPENDENCE (CVL-22) - After Able Service Load Torpedoes in normal stowage. Torpedo landed in carpenter shop. Photo. No. AA-CR-87-2: 1-7.

SECLET

Enclosure (b) to Director Ship Material Serial 001500.

4213

Page 91 of 919 pages. Volume IV.




U.S.O. INDEPENDENCE (CVI-22) - After Able Showing Aircraft Torpedo and Mine, Mk. 24 in ready stownge on hanger deck. Photo. No. AA-CK-27-2541-8.

2 h C h 1 T

Enclosure (b) to Director Ship Meterial Serial 003500.


Thre 197 of 219 pages. Volume IV.



U.S.S. INDEFFNDENCE (CVL-22) - After Able Afterbody of Mk. 13 torpedo that originally was in plane on flight deck. Plane and warhead were blown overboard by blast. Photo. No. AA-CR-87-2541-9.

SECKET

Enclosure (D) to Director Ship Material Serial 001500.



1...5. INLIF.ADEMOL (CVL-22) - After Able Listorted Tail Section of Mine, Mk. 14 that Originally was in plane on flight deck. Plane warread and cylinder were blown overloard by Flost. Thoto. No. AA-CH-87-2541-10.

bulleting (b) to thector this Enterial could be no

large 100 of 219 pages. Volume IV.



onewing terpecoes bridle, low mount, front view, righted to restrict forward movement of terpedoes. (hee excerimental). Photo. No. FA-R-R-R-R-177-3.

22222

Inclorate the to Director with Meterial months of the

Trype 100 of Charge real Charms IV.



U.S.S. LAMSON (DD-367) - Before Able Showing typical placement of special weapon on fantail of destroyers. Photo. No. EA-CR-56-29-2.

Enclosure (D) to Director Ship Material Serial 001500.

Page 196 of 219 pares. Volume IV.



these Mucholic (= 280) a person alleblowing typics — succeed of succeedweapon on family — many and Photos No. 2000 - 2000 - 2000

Billia

Enclosure (1) to difference this Material country of 20 and



U.C.S. MAYMANT (DD-402) - After baker Depth Charte, Mk. VI broken from arbor of K Gun, Frame 130, starboard. Photo. No. Ab-Ch-82-4220-10.

BEQUET

Enclosure (D) to Director Ship Material Serial Colfco.

Page 198 of 219 pages. Volume IV.




U.S.S. MAYRANT (DD-402) - After Baker Depth Charge out of arbor of K Gun at Frame 140, port side. Photo. No. AB-CR-82-4220-9.

LICHI

Pinlocure (D) to Director Ship Material Serial 001500.

Page 199 of 219 pages. Volume IV.



U.S.S. MAYRANT (DD-402) - After Baker Depth Charge, Mk. VI broken from arbor, Frame 140, starboard side, broken linkage. Photo. No. AB-CR-82-4220-8.

Enclosure (D) to Director Ship Material Serial COLECO.

Page 200 of 219 pages. Volume IV.



U.S.S. MAYNANT (LD-402) - After Able Showing torpedo bridles, side view, rigged to restrict forward movement of torpedoes. (Re6 Experimental) Photo, No. AA-CR-63-1704-3.

Enclosure (D) to Director Ship Material Serial 001500.


Page 201 of 219 pages. Bolume IV.



U.S.S. HALPH TALFOT (DD-390) - After Able Torpedo Tube Aft Starboard Side, showing damaged phone box.
Photo. No. AA-CR-63-1703-10.

Enclosure (D) to Director Ship Material Serial 001500.

Page 202 of 219 pages. Volume IV.



U.b.s. FALIP TALEOT (bl-390) - After Alebowing turned residue on painted surisces of tornedo tules, buckled trainerts cost and crecked window in tule train instrument. Thoto. No. In-CR-63-1703-8.


12 12 12 12 T

۲,

-1.

Enclosure (L) to Director Dhi: Naterial Serial (Olifo.

Page 203 of 219 pages. Volume IV.



U.S.S. RHIND (DD-404) - After Able Depth Charges in stern rack, starboard side, showing effects of heat. Photo. No. AA-CR-87-2540-7.

SECLET

Enclosure (D) to Director Ship Material Serial 001500.

Page 204 of 219 pages. Volume IV.



Wherebe relate (LD-40%) - After Able Shown lumbed residue on pointed surfaces of torpedo tutes. Note formers tute erea only surface effected. Hoto. No. 66-C1-63-1695-9.

Ext C = E 1

Inclining the to block in this Reterish correct to At No.

Page 105 of 219 pages. Volume IV.

. :



U.S.S. RHIND (DD-A04) - After Able Showing all torpedoes in startoard mount having moved forward in tubes when TORPHDO STOP TENSION LINKS were broken (cause undertermined). It was evident that torpedoes did not receive sufficient forward motion to actuate inertia starter completely. Photo. No. AA-CR-92-1772-2.

Enclosure (D) to Director Ship Material Serial 001500.

Page 206 of 219 pages. Volume IV.

¥213



Using station of the and a state of the Shain, station of the the let do as forth on footsle deck. Lete distorted bulkherd and is more residue on the constitutions. Letous torus stowed in the collete vicinity were found in perfect conditions, they are forthered to Man, her art, state tox test an report.

The toy Man Annual - 1 - 1.

<u>51517</u>

Enclosure (1) to Director Offip National Constant Constan



U.S.S. HUGHES (LD-410) - After Able Mk. 9 Depth Charges in stern rack showing effects of heat on paint. Photo. No. AA-CR-87-2539-1.

SECHLI

Enclosure (D) to Director Ship Material Serial 001500.

Page 208 of 219 pages. Volume IV.



U.S.S. HUGHES (DD-410) - After Paker Showing torpedoes part was out of learnels of after tube. Photo. No. AB-CR-30-2062-4.

Enclosure (D) to Director Ship Material Seried 000000.

Page 209 of 219 pages. Volume IV.



labor. It is, (13-21) - group to op whowly trajector, while there therein, and may out at thisse bote torpedo in visit, (2000) besterf trajectors. Id. Hota, bo. 21-Ch-79-10,0-7.

1 1 1 1 1 1

Stephen all to theeter ob p Wateriel werich of the


Page 210 of 219 pages. Volume D..



U.S.S. HUGHES (DD-410) - After Baker Showing underside of after torpedo tube upon completion of decontamination work. Flate. No. AB-CR-76-1930-6.

(a) to Director Ship Material Serial 001500.

Page 211 of 219 pages. Volume IV.



U.S.S. HUGHIS (DD-/10) - After Baker Showing torpedo stop tension links carried away. Photo. No. Ab-UH-76-1930-5.

LECRET

Enclosure (D) to Director Ship Material Serial 001500.

Page 212 of 219 pages. Volume IV.



U.D.S. HUGHES (DL-AlC) - After Baker Showing temperoes having slipped part way from tube after guide attude had been sheared. Torpedoes became wedged and bent down from own weight. Photo. No. Al-Ch-70-1980-3.

SECHET

Enclosure (D) to Director Shi: Material Serial CO1500.

Page 213 of 219 pages. Volume IV.

4213



U.S.S. HUGHIS (DD-410) - After Halter Torpedo recovered after it was wrecked by sliding part way from tube when guide atud was sheared. Note afterbody tent just aft of gyro door frame. Photo. No. AB-CR-59-2996-2.

SECHET

Enclosure (D) to Director Ship Meterial Serial 001500.

Page 214 of 219 pages. Volume IV.




U.1.5. PDDML (il-417) - after laker hencein, wrecked service torpedo from target vessel. Photo. No. 25-CR-59-2006-1.

5777FT

Enclosure (b) to birector objective in the end of the birector

Page 215 of 219 pages. Volume IV.




U.S.S. BRACKIN (APA-6A) - refere Able Typical display of Mk. 6 mine on deck of APA's. Photo. No. BA-CR-87-359-5.

SECRET

Enclosure (D) to Director Chip Material Serial 001500.

Page 216 of 219 pages. Volume IV.



U.S.S. ARDC-13 - After Able Showing torpedo tube spoon extension which had been blown, it is believed, from the U.S.S. ANDERSON, DD-411. Photo. No. AA-CR-98-1963-4.

Exclosure (D) to Director Ship Material Serial 001500.

Page 217 of 219 pages. Volume IV.



U.D.D. Ari(-13 - After Able Showing torpedo tube spoon which had been blown, it is believed from the UDS ANDR-DON (LD-All). Photo. No. AA-Ch-08-1963-3.

で作りましま

Enclosure (L) to Director Ship Material Corial CC1500.

Page 218 of 219 pages. Volume IV.



Ustable According to the work the work of the work to the content of which we can be a war, it is interest the content of the

Employme (1) to lineate of indicate the second of the

Inge . 19 of . 1 or er. A show the



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 4	XRD-203-Section 12
AD-366589	XRD-200-Section 9
AD-366590 L	XRD-204-Section 13
AD-366591 ►	XRD-183
∠ AD-366586 ★	XRD-201-Section 10
►AD-367487.	XRD-131-Volume 2-
✓AD-367516¥	XRD- ₹ 143 ✓
✓AD-367493 ८ ✓	XRD-142 ►
AD-801410L 🖍	XRD-138
AD-376831L 🗸	XRD-83
AD-366759	XRD-80
✓AD-376830L ❖	XRD-79 ✓
✓AD-376828L ¥	XRD-76✓
∠ AD-367464. ¾	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
✓AD-367459 🕱	XRD-100✓

Subject: Declassification of Reports

```
✓AD-367491 🔾
                XRD-134-Volume 2
AD-367479 H
                XRD-123 ✓
✓ AD-367478K
                XRD-122 ✓
✓AD-367481 🕊
                XRD-125 ✓
                XRD-159-Volume 2 ringer
 AD-367500 V
✓ AD-367499 ★ XRD-160-Volume 3 ►
 AD-367498 💃
               XRD-161-Volume 4 🗸
 AD-367512 XRD-147
 AD-367511 🗸
                XRD-148
 AD-367465 🗱
                XRD-107 ►
 AD-366733 ✔
                XRD-43
 AD-367477 \
                XRD-121 ✓
 AD-367476 👫
                XRD-120 ℃
 AD-367467 X XRD-109-Volume 1
 AD-367475 💸
                XRD-119 ✓
 AD-367474 🖈
                XRD-118
 AD-367473 🔥
                XRD-117
 AD-367472 🕏
                XRD-116 ✓
 AD-367471 X
                XRD-115 ►
  AD-367466
                XRD-108 ✓
  AD-801405L 🗸
                XRD-113
  AD-367470 💸
                XRD-112 ►
 AD-367469 🚶
               XRD-111 ✓
```

TRC

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

ARDITH JARRETT
Chief, Technical Resource Center